

Appendix 3 Pictures report - General condition of land parcels impacted by RDFS construction

DATE OF REPORT: 10 July 2014

The below pictures report show the actual condition of land parcels identified as utilized for agricultural activities and subsequently impacted by the construction of the Regulating Dam Free Flow Spillway (RDFS) , on 10 July 2014.



East of RNT, in RDFS Spoil Disposal Area – Mr. Bouala



East of RNT, in RDFS Spoil Disposal Area – Mr. Bouala



East of RNT, in RDFS Spoil Disposal Area – Mr. Bounyong



East of RNT, in RDFS Spoil Disposal Area – Ms. Phang



East of RNT, in RDFS Spoil Disposal Area - Ms Phang



East of RNT, in RDFS Spoil Disposal Area – Ms Phang



East of RNT, in RDFS Spoil Disposal Area – Fence Ms. Phang



South/south east of the spillway construction area – Mr. Khamkong



South/south east of the spillway construction area – Mr. Khamkong, Mr. Dii and Mr. Champa



South/south east of the spillway construction area – Mr. Kengta